



Standard Handling Time



PROCEDURE










Remove denture lining bur for thickness of lining surface with cross cut round end tapered carbide bur








Rinse and dry denture surface



Apply Primer on the denture lining area, and then DRY it completely



Apply paste evenly across all surfaces where Primer was applied



After intraoral setting (5+mins.), remove the denture from mouth and carefully trim excess material with a sharp scalpel



10 Use Coarse Point (Black) to smooth the surface and adjust the shape



Use Finishing Wheel (Brown) to finish



12 Lining completed

IMPORTANT TIPS

- Primer Application: 1. Apply Primer to all surface to be lined thin and evenly.
 - 2. Confirm the Primer surface is dry. If wet, air dry completely.
- Paste Application: The paste must be spread evenly across all denture surfaces to be lined prior to insertion to avoid saliva contamination

of the primer. Contamination could result in poor adhesion of the lining material to the denture.

Clean the brush with alcohol after each use. The use of a contaminated brush could lower the adhesion. ·Brush Cleaning:

Notes for cleaning the denture and soft lining material (for patient)

On soft relining

Wipe with a sponge or gauze under running water

On acrylic resin and teeth

Scrub with denture brush


*Oxygenating denture cleaner is recommended to keep denture clean.











IMPORTANT TIPS

- Primer Application: 1. Apply Primer to all surface to be lined thin and evenly.
 - 2. Confirm the Primer surface is dry. If wet, air dry completely.
- Brush Cleaning: Clean the brush with alcohol after each use. The use of a contaminated brush could lower the adhesion.